



**Revision List for Certificate No.: 01/205/5056.03/20**

**Product Tested: Safety Module 1 within  
the COMBIVERT – inverter drive families**



Type Designation	Description	HW / SW Revision	Report-No.:	Certification Status
01 H6 010-0029	Safety Module 1; single/double axis units; STO, SBC	0A / 1.1.0.2 *)	968/EL 499.07/20	valid
01 H6 010-0027	Safety Module 1; single/double axis units; SBC, STO for F6- and S6- family	2B / 1.1.0.2 *)	968/EL 499.07/20	valid
01 H6 010-0028	Safety Module 1; single/double axis units; SBC, STO for H6- family	2B / 1.1.0.2 *)	968/EL 499.07/20	valid
01 H6 010-0026	Safety Module 1:singledouble axis units; SBC, STO for F6- and S6- family	2B / 1.1.0.2 *)	968/EL 499.07/20	valid

\*) SW is not part of the Safety function



Revision List for Certificate No.: 01/205/5056.03/20

Product Tested: Safety Module 1 within  
the COMBIVERT – inverter drive families



List of applicable Inverter Drives:

Type Designation	Description	HW Revision	Safety Module Part No
<b>Type 1</b>			
xxH6ABx-xxxx	H6 Single Axis Module 0,75 - 110 kW, 565 DC Control Unit Type A	0A	01H6210-0029 01H6010-0028
xxH6BBx-xxxx	H6 Double Axis Module 0,75 - 4 kW, 565 DC Control Unit Type B	0A	01H6210-0029 01H6010-0028
xxS6A1x-xxxx	S6 servo drive 0,75 – 5,5 kW, 400 AC Control Unit Type A, Multifunction - Encoderinterface	10	01H6010-0027
xxF6A1x-xxxx	F6 frequency inverter 0,75 - 400 kW, 400 AC Control Unit Type A, Multifunction – Encoderinterface	10	01H6010-0027

Document Revision:

Date	Rev.	Description / Changes	Author
2015-05-20	1.0	Initial creation, based on Report-No.: 968/EL 499.02/15	jz/A-FS
2016-11-17	1.1	Supplementary inspection, based on Statement.: 968/EL 499.03/16	jz/A-FS
2019-07-29	1.2	Ba: Mod der Baureihe Combivert (Klemmleiste Buchsen – neue Varianten)	Ba/A-FS
2020-05-26	1.3	SM2/3 wurde entfernt / Baugruppe 01H6010-0019 wurde entfernt (Bericht: 968/EL 499.07/20)	Ba/A-FS